

Dear Öhlins Asia Distributor

(W24) 15.06.2017

Information update

HO 611 Honda MSX125 SF (Rear suspension) model 2016 cannot fit with model 2017 both ABS and without ABS due to the reason of position change for Oil filling screw (see below pictures). The bracket cannot install in the same position.

Company will develop and find solution to fit with model 2017. For further information update, company will let you know later on.

Model 2016



Model 2017



Best regards,

Öhlins Asia

